Svensk Binär Teknik

Temperature and humidity sensor, -20 to + 80 ° C, 0 to 90% rH with 1 x RJ45. Accessories for GUDE

FEATURES

Box temperature and humidity sensor for wall mounting
Sensor detected automatically
Can be connected with RJ45 STP cable up to 40 meters from the control
Temperature and humidity range: -20 ° C to + 80 ° C, + / -0.5 ° C, 0 to 90% rH, +/- 3%