

4-20mA transmitter for PT100, including 3-wire PT.100 sensor, steel and 2M steel Flex cable. Supply voltage 24VDC.

FEATURES

- Pt.100 transmitter for your mounting
- 2 - 3-wire pt.100 sensor (red to 16, 2 x blue to 18 and A2)
- 24v to 15 and 26
- 4 - 20 mA power Out of 16 and 26
- 4 - 20 mA The output gives power to PLC / instrument
- Including PT100 feel with 80mm, Ø4MM Steel Tips
- 2 meter Flex cable
- Supply voltage: 24VDC
- Dim : H 74 x L 105 x B 22 mm





SPECIFICATIONS

Operating Temp.	:	0 - 50° C
Forsyning	:	24 VDC 2 W
Montering	:	DIN skinne eller panelmontage
Måleområde	:	-20 - 130 °C
Stik	:	Skrueterminaler
Udgange	:	4-20mA. Strøm ved: -20 °C 4 mA 130 °C 20 mA

