

## NPOWER-GU-TH

### Temperature/humidity meter for GUDE NPOWER PDUs, -20 to +80°C, 0-100rH

#### FEATURES

- Temp/humidity meter with RJ45 for GUDE
- Up to 40 meters
- Temperature: -20°C to +80°C at  $\pm 2^\circ\text{C}$  (maximum) and  $\pm 1^\circ\text{C}$  (typical)
- Humidity: 0-100% at  $\pm 3\%$  (typical) and 10-80% at  $\pm 2\%$  (typical)
- Sensor housing: plastic
- Dimensions: 42 x 20 x 35 mm
- Weight: 29g

